

CODIX 555 with totaliser and 2 limit values



Now available with serial interface and set-up software EzControl!

Your benefit

- Programmable input characteristic curve with up to 24 control points
- Integration function (totaliser) or limit values reset keys
- Display-Hold or reset input for the integration function (totaliser) or for the limit values
- Very big keys for use with gloves
- Input for key-lock
- very bright display

Input range

0 ... 20 mA, 4 ... 20 mA; 0 ... 10 V
2 ... 10 V; ± 10 V

Outputs

2 limit values with programmable hysteresis and programmable signal behaviour, relays with change-over contact or optocoupler

More advantages

- Auxiliary power supply output for measuring transducer/sensor
- optional serial interface

Technical data

Miscellaneous Data

Display	5 digit red LED 14.2 mm high
Display range	-19999 ... 99999, with leading zeros suppression
Out of Range Indication	Under-range uuuuu / Over-range ooooo
Data storage	EEPROM, 1 Million storage cycles or 10 Years
Test voltages	EN 61010 Part 1 ; overvoltage category 2, level 2
EMC	Interference emissions EN 50081-2 / EN 55011 Class B

Interference resistance EN 61000-6-2

AC power supply 90 ... 260 V AC/max. 6 VA
external fuse 100 mA/T

DC power supply 10 ... 30 V DC, max. 2 W, galvanically isolated
with inverse polarity protection
external fuse 250 mA/T

Mains Hum Filter digital filter 50 Hz or 60 Hz, programmable

Measurement ranges

Current input (DC)	Ranges 0 ... 20 mA, 4 ... 20 mA
Resolution	2 μ A
Voltage drop	max. 2 V bei 20 mA
Max. current	50 mA
Voltage input(DC)	Ranges 0 ... 10 V, 2 ... 10 V, ± 10 V
Resolution	1 mV
Input resistance	> 2 M Ω
Max. voltage	± 30 V
Measuring speed	approx. 2 measurements/s
Linearity	< 0,1% ± 1 Digit for the whole measuring range at an ambient temperature of 20°C
Zero calibration	automatic
Temperature drift	100 ppm/K

Weight approx. 220 g

Protection IP 65 (front)

Ambient temperature -20 ... +65 °C

Storage temperature -40 ... +85 °C

Digital inputs

Input MPI* Function of the inputs depending on set up

1. Function Display-Hold to stop the instantaneous value

2. Function Reset Reset the alarm value

Alarm Latch

3. Function Reset-Totalizer Resetting the Totalizer

Outputs

Alarm 1/Alarm output 2

Relay output with volt-free changeover contacts can be setup as normally closed or normally open

Switching voltage 250 V AC/300 V DC

Switching current max. 3 A AC/DC, min. 30 mA DC

Switching power 2000 VA / 50 Ω

or NPN-optocoupler with open collector and open emitter

Switching power: 30 V DC/15 mA

Auxiliary power supply output for measuring transducer/sensor

AC models voltage output 10 V DC $\pm 2\%$, 30 mA and
voltage output 24 V DC $\pm 15\%$, 50 mA

DC models only voltage output 10 V DC $\pm 2\%$, 30 mA

Interface


Available options RS232, RS485, RS422

Baud rate 600, 1200, 2400, 4800, 9600, 19200 programmable

Address 00 ... 99 programmable


*MPI: Multi Purpose Input

Dimensions:



Connections:

Rear side view





Measuring- and control inputs as well as auxiliary signals

Power supply and limit outputs

Interface

Power supply and alarm outputs




	DC version	AC version
7	10 ... 30 V DC	90 ... 260 V AC (N~)
8	GND4 (0 V DC)	90 ... 260 V AC (L~)

Current measurement




1	Current input (I) 0 ... 20 mA / 4 ... 20 mA
2	GND1 (Analog)

Voltage measurement



2	GND1 (Analog)
3	Voltage input (U) 0 ... 10 V, 2 ... 10 V, -10 ... +10 V

Control inputs and auxiliary power supply (U_{out})



1 Alternatively connect directly to DC supply (galvanic separation of control and measurement inputs)

9	GND3 (for U _{out})
10	U _{out} +10 V/30 mA
11	U _{out} +24 V/50 mA only for power supply 90 ... 260 V AC
8	MP-Input "Reset-Alarm-Latch/Display-Hold/Reset Totalisator"
7	GND2 (KEY/MPI)
6	Keypad lock-out "Key"

Interface

X3 1 2 3 4 5

	RS232	RS485	RS422
1	GND	-	-
2	RxD	DO+/RI+	RI+
3	TxD	DO-/RI-	RI-
4	-	-	DO+
5	-	-	DO-

Application:

- Level measurement
- Flow measurement
- Pressure measurement
- Revolution measurement

Serial interface

- For data transmission and documentation
- Connection for programmable logic controllers
- Programming via PC

Delivery includes:

- Process display
 - Screw terminal, 8-pole, RM 5.08
 - Screw terminal, 11-pole, RM 3.81
 - Screw terminal, 5-pole, RM 3.81(*)
 - Clamping bracket
 - Gasket
 - Multilingual operating instructions
 - 1 set of self-adhesive symbols
- * only with the interface option

Order code:

6.555.01X.X0X

